

L Number	Hits	Search Text	DB	Time stamp
1.	32025	((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4).clm.	USPAT; US-PGPUB; EPO; JPO	2003/08/06 16:10
2	2694	((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4).clm.) and (wheel caliper).clm.	USPAT; US-PGPUB; EPO; JPO	2003/08/06 13:05
3	6	((((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4).clm.) and (wheel caliper).clm.) and (stress near2 axis).clm.	USPAT; US-PGPUB; EPO; JPO	2003/08/06 13:05
4	35	((((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4).clm.) and (stress near2 axis).clm.) and (stress near2 axis).clm.	USPAT; US-PGPUB; EPO; JPO	2003/08/06 13:34
5	35	((((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4).clm.) and (stress near2 axis).clm.) and (stress near2 axis).clm.	USPAT; US-PGPUB; EPO; JPO	2003/08/06 13:05
6	10	((((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4).clm.) and (stress near2 axis).clm.) and (stress near2 axis)	USPAT; US-PGPUB; EPO; JPO	2003/08/06 13:06
7	11	((((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4).clm.) and (stress near2 axis).clm.) and (wheel caliper)	USPAT; US-PGPUB; EPO; JPO	2003/08/06 15:57
8	41	((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4).clm.) near3 embed\$5.clm.	USPAT; US-PGPUB; EPO; JPO	2003/08/06 15:59
9	0	((((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4).clm.) near3 embed\$5.clm.) and (principal).clm.	USPAT; US-PGPUB; EPO; JPO	2003/08/06 16:02
10	5	((((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4).clm.) near3 embed\$5.clm.) and (principal)	USPAT; US-PGPUB; EPO; JPO	2003/08/06 16:00
11	12	((((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4).clm.) near3 embed\$5.clm.) and (axis axes).clm.	USPAT; US-PGPUB; EPO; JPO	2003/08/06 16:03
12	96	((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4).clm.) and (embedded near2 (detect\$4 determin\$4 sens\$4 transducer gauge cell monitor\$4).clm.	USPAT; US-PGPUB; EPO; JPO	2003/08/06 16:14

13	15	((((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4)).clm.) and (embedded near2 (detect\$4 determin\$4 sens\$4 transducer gauge cell monitor\$4)).clm.) and ((stress strain central principal) near3 (axis))	USPAT; US-PGPUB; EPO; JPO	2003/08/06 16:19
14	4	((((force load stress) near2 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 calculat\$4)).clm.) and (embedded near2 (detect\$4 determin\$4 sens\$4 transducer gauge cell monitor\$4)).clm.) and caliper	USPAT; US-PGPUB; EPO; JPO	2003/08/06 16:19